

INCOMING INSPECTION REPORT for June 2013

TOYO CORPORATION
Reported on 7/22/2013

COMPANY : ELECTROCHEM,INC

No.	Model	Description	S/N	PO#	Date received	Rcv. Qty.	Fail. Qty.	Software Version	Failure Description (Refer to Failure Report for details)
1	EC-TP1-090T	EC-TP1-090T	Y	E96841	6/13/2013	1	0	N	N
2	HFC-05-02HR	FC-05-02-H2R	E4746	E96696R01	6/13/2013	1	0	N	N
3	HFC-05-02	FC-05-02	E4742	E96809	6/13/2013	1	0	N	N
4	HFC-05-02	FC-05-02	E4743	E96809	6/13/2013	1	0	N	N
5	HFC-05-02	FC-05-02	E4744	E96809	6/13/2013	1	0	N	N
6	HFC-05-02	FC-05-02	E4745	E96809	6/13/2013	1	0	N	N
7	EC-GSSL1005	EC-GS-SIL-10-05SP	N	31134000	6/13/2013	4	0	N	N
8	EC-NM-212	EC-NM-212	N	31134000	6/13/2013	1	0	N	N
9	EC-NM-212	EC-NM-212	N	31134000	6/13/2013	1	0	N	N
10	EC-CC1-060	EC-CC1-060	N	31134100	6/13/2013	1	0	N	N
11	EC-CC1-060	EC-CC1-060	N	31134100	6/13/2013	1	0	N	N
12	EC-CC1-060	EC-CC1-060	N	31134100	6/13/2013	1	0	N	N
13	EC-CC1-060	EC-CC1-060	N	31134100	6/13/2013	1	0	N	N
14	EC-CC1-060	EC-CC1-060	N	31134100	6/13/2013	1	0	N	N
15	EC-CC1-060	EC-CC1-060	N	31134100	6/13/2013	1	0	N	N